

# Assembly Instructions Training Table Cable Management Enclosure

## **Part Numbers:**

5500-3-100-36, 5500-3-100-48

5500-3-100-60, 5500-3-100-72



### Training Table sold separately.

Address: 10152 Liberty Lane


Chisago City, Minnesota, 55013

**United States of America** 

Phone: 651-213-1333


Fax: 800-418-6897

www.kendallhoward.com










Secure right and left ends to the bottom of the Cable Management Enclosure with 1/4-20" screws.


#### Step 2:




- Detach the modesty panel from the leg kit.
- Remove screws from the rear leg kit that fasten it to the table top.
- Slide the Cable Enclosure around the modesty panel. C.
- Re-insert screws securing the modesty panel and cable enclosure to the leg kit.

Step 3:

Step 1:



Secure the lock base just behind the grommet opening with the 1/4-20" screws.



- Secure female hinges to the enclosure bottom with the M5x10 screws. Ensure hole openings face toward each other.
- Secure one male hinge to enclosure door bottom with M5x10 screws. Insert should be facing the outside of the door.
- C. Insert the installed male hinge into the female hinge. Take the remaining male hinge and insert into the opposing female hinge and secure to the door with M5x10 screws.

#### For details about product warranty, please visit www.kendallhoward.com

DISCLAIMER: Kendall Howard LLC. endeavors to make this manual accu-

rate and complete. However, Kendall Howard LLC makes no representations or warranties of any kind, expressed or implied, about whether the use of products contained herein would infringe any rights or the correctness, accuracy or reliability of the information contained herein or that said information covers all details, conditions or variations. The information herein does not provide for every possible contingency in connection with the installation or use of the product(s). The information contained in this document is subject to change without notice or obligation. Kendall Howard LLC assumes no responsibility for the accuracy, completeness or reliability of the information contained in this document. Any reliance placed on the