


Assembly Instructions Performance Plus® Accessory Bar

Part Numbers:

7000-3-536-00, 7000-3-548-00

7000-3-560-00, 7000-3-572-00



Workbench and other accessories not included with Accessory Bar.

Address: 10152 Liberty Lane


Chisago City, Minnesota, 55013

United States of America

Phone: 651-213-1333

Fax: 800-418-6897

www.kendallhoward.com





Step 1:



Slide both mounting brackets on either end of the Accessory Bar. Install the bolts through the mounting bracket into the desired position on upright. Install the flat washers and nuts from the backside.

Step 2:



Use the screwdriver and wrench to secure hardware in place.

For details about product warranty, please visit www.kendallhoward.com

DISCLAIMER: Kendall Howard LLC. endeavors to make this manual accurate and complete. However, Kendall Howard LLC makes no representations or warranties of any kind, expressed or implied, about whether the use of products contained herein would infringe any rights or the correctness, accuracy or reliability of the information contained herein or that said information covers all details, conditions or variations. The information herein does not provide for every possible contingency in connection with the installation or use of the product(s). The information contained in this document is subject to change without notice or obligation. Kendall Howard LLC assumes no responsibility for the accuracy, completeness or reliability of the information contained in this document. Any reliance placed on the information is therefore strictly at your own risk.